

REPORT

Level One Inspection and Testing Services

Meridian Estate Stage 9C, Lots 9082 to 9116 and Lot GG

Prepared for:

Grosvenor Lodge Pty Ltd

August 2020

Our Ref: 3807351.09C.v1

25 Metcalf Street, Dandenong South, Vic 3175, Australia www.chadwickgeotechnics.com.au

Document Control

Title: Lev	Title: Level One Inspection and Testing Services											
Date	Version Description Prepared by: Reviewed by: Authorised by:											
20-08-20	1	Level One report, 3807351.09C	RHB	RHB	TJJC							

Distribution:

Grosvenor Lodge Pty Ltd Chadwick Geotechnics Pty Ltd (FILE) 1 electronic copy

1 electronic copy

Table of contents

1	Introduction	1
2	Project details	1
3	Geology	1
4	Specification	2
5	Inspection and testing	2
6	Conclusion	3
7	Applicability	4

Appendix A : Density Test Location Plan
Appendix B : Table of field density results

Appendix C NATA endorsed laboratory reports

Appendix D: Controlled fill certificates

1 Introduction

Chadwick Geotechnics Pty Ltd (Chadwick Geotechnics) was engaged by Grosvenor Lodge Pty Ltd, to provide Level 1 Geotechnical Inspection and Testing services for the earthworks within Stage 9C of the Meridian Estate in Clyde North.

2 Project details

The project included the preparation and filling of lot's 9082 to 9116 and Lot GG. The specification required the earthworks to be completed under Level 1 Supervision, that is, full-time Inspection and Testing of the earthworks. Chadwick Geotechnics were onsite for the duration of the earthworks program.

The location of the site is shown in figure 1 below.



Figure 1: Approximate site location (Image sourced from Nearmaps)

3 Geology

Published information¹ shows that the site is underlain by various geologies listed as follows;

- Quaternary Age Unnamed dune deposits Formation (Qd1) comprising of sand, clay and calcareous sand.
- Quaternary Age Unnamed swamp and lake deposits Formation (Qm1) comprising of silt and clay.
- Palaezoic Age Murrindindi Supergroup (Sm) comprising of mudstone and sandstone

-

¹ BIBBY, L.M., 2004. Simplified 1: 4 000 000 Geology of Victoria. Geological Survey of Victoria Special Publication. GeoScience Victoria.

 Neogeone Age Baxter Sandstone Formation (Nxx) comprising of sandstone, conglomerate, siltstone and ironstone.

4 Specification

A summary of the specification is shown below:

Compaction Requirement 95 % Standard Compaction

5 Inspection and testing

The inspection and testing of earthworks has been carried out in accordance with AS3798-2007, 'Guidelines on earthworks for commercial and residential developments', with a frequency of field density tests as per a type one project (large scale operation). Compaction control laboratory testing was undertaken in our NATA accredited laboratories in accordance with AS1289 'Methods of Testing Soils for Engineering Purposes'.

Prior to fill being placed the subgrade was inspected. The inspections were performed in accordance with the Level 1 guidelines presented in AS 3798–2007 Section 5.5. No soft spots were encountered during the inspections, the area was found to be firm and free of vegetation and other deleterious material.

Full time Level 1 Geotechnical Inspection and Testing of the filling operations commenced on 17 May 2016 and was completed on 23 October 2019. During this period Chadwick Geotechnics observed the earthworks at the times (as the filling works were intermittent) the earthworks contractor was placing fill. This included the supply of material, conditioning of material (moisture conditioning), placement and compaction of the fill material.

All fill material was placed in lift sequences and Chadwick Geotechnics verified that the surface of the stripped area, and that of additional lifts, was thoroughly scarified and moisture conditioned prior to placement of additional layers to prevent delamination at the layer interface.

Field density and moisture content testing was carried out using a calibrated portable density and moisture gauge in accordance with AS 1289.5.8.1. The HILF rapid compaction test was used for peak converted wet density determinations in accordance with AS 1289.5.7.1. Test locations were recorded using a handheld GPS unit. A site plan showing the field density test locations is provided in Appendix A.

A total of twenty-two (22) tests were performed during the filling process.

The results show that all tests achieved the specification requirements for the project.

A summary table of Hilf density tests is provided in Appendix B and the laboratory test reports are provided in Appendix C.

6 Conclusion

On the basis of our inspections and after considering all test results relating to the project, it is our opinion, so far as it is able to be determined, that:

- The materials used by the earthworks contractor met the geotechnical property requirements of the specification.
- The sourced fill was considered to be natural and clean and suitable for use at the site.
- The fill material placed was tested at a suitable frequency in accordance with AS 3798-2007-Table 8.1 and the results indicate the compacted clay achieved the density requirement of the specification.
- Given the consistent construction practices followed by the earthworks contractor and as witnessed by the Chadwick Geotechnics, combined with the satisfactory verification of test results achieved, it is inferred that areas of the site between test locations were performed to the same standard as those areas that have been tested.

It is our opinion that the earthworks undertaken have been performed in accordance with the requirements of Section 8.2 of AS3798-2007 - Level 1 Inspection and Testing.

7 Applicability

This report has been prepared for the exclusive use of our client Grosvenor Lodge Pty Ltd in good faith and in accordance with the Chadwick Geotechnics quality system for the earthworks filling at the site.

This report is based on the nature of the project and the prevailing conditions between 17 May 2016 to 23 October 2019. No responsibility or liability will be accepted, and Chadwick Geotechnics is indemnified to the full extent permitted by law in respect of the use of this report where there has been a change in the nature of the project or the conditions on site that may alter or affect the conclusions of this report.

Should you require any further information regarding this report, please do not hesitate to contact the undersigned on (03) 8796 7900.

Chadwick Geotechnics Pty Ltd

Report prepared by:

Authorised for Chadwick Geotechnics Pty Ltd by:

Robert Barden

Timothy Chadwick

Geotechnical Engineer

Project Director

© Chadwick Geotechnics Pty Ltd.

Other than for the exclusive use of our client Grosvenor Lodge Pty Ltd, no part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise, without the prior written permission of Chadwick Geotechnics Pty Ltd.

www.chadwickgeotechnics.com.au

Appendix A: Density Test Location Plan



Appendix B: Table of field density results



Hilf Summary Table

3807351.009C Meridian Estate Stage 9C

Chadwick Geotechnics 25 Metcalf Street Dandenong South VIC 3175 Tel: (03) 8796 7900 Fax: (03) 8796 7944



Report No	Sample No	Date	Test Number	Location [E]	Location [N]	Layer	Density Ratio HILF test (≥95%)	Moisture Variation From OMC	Pass / Fail	Remarks
380735 - 26	1606450	17/05/2016	80	354849	5782305	Layer 1	100	0.5 wet	Pass	
380735 - 26	1606451	17/05/2016	81	354881	5782304	Layer 1	106	0.5 wet	Pass	
380735 - 26	1606452	17/05/2016	82	354831	5782280	Layer 1	100	0.5 wet	Pass	
380735 - 26	1606453	17/05/2016	83	354902	5782228	Layer 1	103.5	2.0 dry	Pass	
380735 - 26	1606454	17/05/2016	84	354894	5782276	Layer 1	100	0.5 wet	Pass	
380735 - 26	1606455	17/05/2016	85	354855	5782268	Layer 1	100.5	0.5 wet	Pass	
380735 - 29	1606695	21/05/2016	98	354831	5782207	Layer 2	99	3.0 wet	Pass	
380735 - 29	1606696	21/05/2016	99	354835	5782243	Layer 2	103	0.5 wet	Pass	
380735 - 29	1606697	21/05/2016	100	354860	5782247	Layer 2	102.5	1.0 dry	Pass	
380735 - 29	1606698	21/05/2016	101	354816	5782284	Layer 2	98.5	2.0 dry	Pass	
380735 - 29	1606699	21/05/2016	102	355055	5782322	Layer 2	101	2.0 dry	Pass	
380735 - 34	1607236	3/06/2016	122	354882	5782202	Layer 1	102.5	0.5 wet	Pass	
380735 - 34	1607237	3/06/2016	123	354880	5782219	Layer 1	103	1.0 wet	Pass	
380735 - 34	1607238	3/06/2016	124	354887	5782234	Layer 1	99.5	0.5 wet	Pass	
380735 - 34	1607239	3/06/2016	125	354861	5782208	Layer 1	99	1.0 wet	Pass	
380735 - 34	1607240	3/06/2016	126	354864	5782228	Layer 1	100.5	0.5 wet	Pass	
380735 - 34	1607241	3/06/2016	127	354860	5782258	Layer 1	103	0.5 wet	Pass	
380735 - 48	1610555	7/09/2016	167	354716	5782414	Roadway	104.5	2.5 dry	Pass	
HDR:W17DS00439	1650	8/05/2017	1	354861	5782283		108.5	0.5 dry	Pass	
HDR:W17DS00439	1651	8/05/2017	2	354801	5782273		99.5	0.5 wet	Pass	
HDR:W17DS00439	1652	8/05/2017	3	354774	5782306		106.5	OMC	Pass	
HDR:W17DS00439	1653	8/05/2017	4	354816	5782323		94	0.5 wet	Fail	See retest 8395
HDR:W17DS00439	1654	8/05/2017	5	354861	5782334		95.5	OMC	Pass	
HDR:W17DS02277	8395	10/11/2017	1	354820	5782321		103.5	3.0 dry	Pass	Retest of 1653
HDR:W19DS02116	7421	25/09/2019	1	354728	5782312		103	3.0 wet	Pass	
HDR:W19DS02116	7422	25/09/2019	2	354730	5782287		103.5	OMC	Pass	
HDR:W19DS02117	7423	25/09/2019	1	354757	5782359		108.5	3.0 dry	Pass	
HDR:W19DS02123	7438	26/09/2019	1	354721	5782364	31.050	101.5	2.0 dry	Pass	
HDR:W19DS02123	7439	26/09/2019	2	354737	5782314	31.120	100	1.0 dry	Pass	



Hilf Summary Table

3807351.009C Meridian Estate Stage 9C

Chadwick Geotechnics 25 Metcalf Street Dandenong South VIC 3175 Tel: (03) 8796 7900 Fax: (03) 8796 7944



Report No	Sample No	Date	Test Number	Location [E]	Location [N]	Layer	Density Ratio HILF test (≥95%)	Moisture Variation From OMC	Pass / Fail	Remarks
HDR:W19DS02133	7464	30/09/2019	1	354731	5782321	30.700	108.5	3.0 dry	Pass	
HDR:W19DS02133	7465	30/09/2019	2	354738	5782285	30.860	101	2.0 dry	Pass	
HDR:W19DS02143	7519	1/10/2019	1	354716	5782349	30.880	99.5	1.9 wet	Pass	
HDR:W19DS02154	7546	2/10/2019	1	354726	5782286	30.800	99	0.5 wet	Pass	
HDR:W19DS02154	7547	2/10/2019	2	354711	5782328	30.700	97.5	2.0 wet	Pass	
HDR:W19DS02168	7582	3/10/2019	1	354735	5782298	31.260	101	1.0 wet	Pass	
HDR:W19DS02168	7583	3/10/2019	2	354702	5782379	30.560	97	3.0 wet	Pass	
HDR:W19DS02181	7613	4/10/2019	1	354895	5782729	31.100	105	2.0 dry	Pass	
HDR:W19DS02181	7614	4/10/2019	2	354891	5782689	31.170	102.5	0.5 dry	Pass	
HDR:W19DS02181	7615	4/10/2019	3	354722	5782332	31.280	101.5	2.0 dry	Pass	
HDR:W19DS02181	7616	4/10/2019	4	354726	5782300	31.150	100.5	0.5 dry	Pass	
HDR:W19DS02199	7662	7/10/2019	1	354684	5782388	29.647	102	0.5 dry	Pass	
HDR:W19DS02199	7663	7/10/2019	2	354700	5782276	29.990	99	OMC	Pass	
HDR:W19DS02229	7778	10/10/2019	1	354765	5782241	31.170	104	2.0 dry	Pass	
HDR:W19DS02242	7816	11/10/2019	1	354767	5782295	31.960	97	0.5 dry	Pass	
HDR:W19DS02242	7817	11/10/2019	2	354745	5782221	30.830	95.5	2.0 wet	Pass	
HDR:W19DS02242	7818	11/10/2019	3	354764	5782212	30.850	98	0.5 wet	Pass	
HDR:W19DS02250	7838	14/10/2019	1	354741	5782259	31.160	99.5	OMC	Pass	
HDR:W19DS02250	7839	14/10/2019	2	354753	5782213	31.070	97	2.0 wet	Pass	



Hilf Summary Table

3807351.009C Meridian Estate Stage 9C

Chadwick Geotechnics 25 Metcalf Street Dandenong South VIC 3175 Tel: (03) 8796 7900 Fax: (03) 8796 7944



Report No	Sample No	Date	Test Number	Location [E]	Location [N]	Layer	Density Ratio HILF test (≥95%)	Moisture Variation From OMC	Pass / Fail	Remarks
HDR:W19DS02250	7840	14/10/2019	3	354777	5782203	31.250	95	OMC	Pass	
HDR:W19DS02250	7841	14/10/2019	4	354762	5782242	31.220	96.5	OMC	Pass	
HDR:W19DS02261	7873	15/10/2019	1	354772	5782224	31.167	100	OMC	Pass	
HDR:W19DS02261	7874	15/10/2019	2	354749	5782219	31.045	96.5	OMC	Pass	
HDR:W19DS02276	7942	16/10/2019	1	354739	5782254	31.440	100	OMC	Pass	
HDR:W19DS02276	7943	16/10/2019	2	354773	5782208	31.520	98.5	OMC	Pass	
HDR:W19DS02276	7944	16/10/2019	3	354775	5782302	32.160	100	OMC	Pass	
HDR:W19DS02292	7996	18/10/2019	1	354751	5782252	31.520	102.5	0.5 dry	Pass	
HDR:W19DS02292	7997	18/10/2019	2	354742	5782208	31.670	101.5	2.0 dry	Pass	
HDR:W19DS02292	7998	18/10/2019	3	354763	5782203	31.730	98	1.0 wet	Pass	
HDR:W19DS02315	8059	22/10/2019	1	354774	5782190	31.850	98.5	OMC	Pass	
HDR:W19DS02329	8110	23/10/2019	1	354784	5782265	32.200	101	OMC	Pass	
HDR:W20DS00028	102	13/01/2020	1	354778	5782402	32.657	102	OMC	Pass	

Appendix C NATA endorsed laboratory reports

Ph: +61 3 8796 7900 Fax: +61 3 8796 7944



Customer: Grosevnor Lodge Pty Ltd

Customer Address: 48 Healy Road, Dandenong Sth, Vic 3175

Project: Meridian Estate

Location: Clyde North

Customer Order No.: -

HILF DENSITY RATIO REPORT

Testing performed and reported at our Dandenong South Laboratory 21712

Report Number:

380735 - 26

23/05/16

1

of 1

Report Date:

Page:

C.G Order No: 151744

Test Method: AS1289.5.7.1

Sample No.:	1606450	1606451	1606452	1606453	1606454	1606455		
ID No.:	1	2	3	4	5	6		
Lot No.:	-	-	-	-	-	-		
Date Sampled:	17/05/2016	17/05/2016	17/05/2016	17/05/2016	17/05/2016	17/05/2016		
Time Sampled:	am/pm	am/pm	am/pm	am/pm	am/pm	am/pm		
Date Tested:	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016	19/05/2016		
Material Source:	Site Derived							
Material Description:	Silty Clay							
To Be Used As	Fill	Fill	Fill	Fill	Fill	Fill		
	E 354849	E 354881	E 354831	E 354902	E 354894	E 354855		
Sample Location :	N 5782305	N 5782304	N 5782280	N 5782228	N 5782276	N 5782268		
	Layer 1							
Layer Depth (mm):	150	150	150	150	150	150		
Test Depth (mm):	125	125	125	125	125	125		
Sampling Procedure:	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)		
Max Size (mm):	19.0	19.0	19.0	19.0	19.0	19.0		
Oversize Wet (%):	0	0	0	0	0	0		
Fld. Wet Density (t/m³) AS 1289.5.8.1:	2.09	2.12	2.02	2.09	2.07	2.08		
Fld. Moisture Content (%) AS1289.2.1.1:	-	-	-	-	-	-		
PCWD (t/m ³):	2.09	1.99	2.02	2.02	2.07	2.07		
APCWD (t/m ³)	-	-	-	-	-	-		
O.M.C (%) AS1289.5.7.1:	-	-	-	-	-	-		
Moisture Ratio (%) AS1289.5.4.1:	-	-	-	-	-	-		
Moisture Variation (of omc):	0.5% (wet)	0.5% (wet)	0.5% (wet)	2% (dry)	0.5% (wet)	0.5% (wet)		
Adjusted Moisture Variation (of omc):	-	-	-	-	-	-		
Compactive Effort:	Standard	Standard	Standard	Standard	Standard	Standard		
Hilf Density Ratio (%):	100.0	106.0	100.0	103.5	100.0	100.5		
Min Hilf Density Ratio (%):	95	95	95	95	95	95		

Remarks:





Accredited for compliance with ISO/IEC 17025. The results of tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

APPROVED SIGNATORY

Form No.: CG.315.002 Issue Date: 19/02/2013

M.Robinson

Ph: +61 3 8796 7900 Fax: +61 3 8796 7944



Customer: Grosevnor Lodge Pty Ltd

Customer Address: 48 Healy Road, Dandenong Sth, Vic 3175

Project: Meridian Estate

Location: Clyde North

Customer Order No.: -

HILF DENSITY RATIO REPORT

Report Number:

380735 - 29

of 1

Report Date: 23/05/16

C.G Order No: -

Test Method: AS1289.5.7.1

rest Metriou. AS 1269.5.7.

Page: 1

Testing performed and reported at our Dandenong South Laboratory 21712

	4000005	4000000	400000=	4000000	4000000		
Sample No.:	1606695	1606696	1606697	1606698	1606699		
ID No.:	1	2	3	4	5		
Lot No.:	-	-	-	-	=		
Date Sampled:	21/05/2016	21/05/2016	21/05/2016	21/05/2016	21/05/2016		
Time Sampled:	am	am	am	am	am		
Date Tested:	23/05/2016	23/05/2016	23/05/2016	23/05/2016	23/05/2016		
Material Source:	Site Derived						
Material Description:	Silty Clay						
To Be Used As	Fill	Fill	Fill	Fill	Fill		
	E 354831	E 354835	E 354860	E 354816	E 355055		
Sample Location :	N 5782207	N 5782243	N 5782247	N 5782284	N 5782322		
Cample 200alion	Layer 2						
	.,.	.,.	.,,	.,.	.,.		
Layer Depth (mm):	150	150	150	150	150		
Test Depth (mm):	125	125	125	125	125		
Sampling Procedure:	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)		
Max Size (mm):	19.0	19.0	19.0	19.0	19.0		
Oversize Wet (%):	0	0	0	0	0		
Fld. Wet Density (t/m³) AS 1289.5.8.1:	2.04	2.10	2.03	2.04	1.99		
Fld. Moisture Content (%) AS1289.2.1.1:	-	-	-	•	-		
PCWD (t/m ³):	2.06	2.03	1.98	2.07	1.97		
APCWD (t/m ³)	-	-	-	-	-		
O.M.C (%) AS1289.5.7.1:	-	-	-	-	-		
Moisture Ratio (%) AS1289.5.4.1:	-	-	-	-	-		
Moisture Variation (of omc):	3% (wet)	0.5% (wet)	1% (dry)	2% (dry)	2% (dry)		
Adjusted Moisture Variation (of omc):	-	-	-	-	-		
Compactive Effort:	Standard	Standard	Standard	Standard	Standard		
Hilf Density Ratio (%):	99.0	103.0	102.5	98.5	101.0		
Min Hilf Density Ratio (%):	95	95	95	95	95		

Remarks:





Accredited for compliance with ISO/IEC 17025. The results of tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

APPROVED SIGNATORY

MA

Form No.: CG.315.002

Issue Date: 19/02/2013

M.Robinson

Ph: +61 3 8796 7900 Fax: +61 3 8796 7944



Customer: Grosevnor Lodge Pty Ltd

Customer Address: 48 Healy Road, Dandenong Sth, Vic 3175

Project: Meridian Estate

Location: Clyde North

HILF DENSITY RATIO REPORT

380735 Report Number:

09/06/16

C.G Order No: 152054

Report Date:

AS1289.5.7.1 Test Method:

Page:

of

- 34

Customer Order No.: -

Testing performed and reported at our Dandenong South Laboratory 21712

Sample No.:	1607236	1607237	1607238	1607239	1607240	1607241			 -
ID No.:	1	2	3	4	5	6			
Lot No.:			-	-	-				 1
Date Sampled:	3/06/2016	3/06/2016	3/06/2016	3/06/2016	3/06/2016	3/06/2016			
Time Sampled:	am/pm	am/pm	am/pm	am/pm	am/pm	am/pm			+
Date Tested:	6/06/2016	6/06/2016	6/06/2016	6/06/2016	6/06/2016	6/06/2016			 -
Material Source:	Site Derived	Site Derived	Site Derived	Site Derived	Site Derived	Site Derived			-
	Silty Clay	Silty Clay	Silty Clay	Silty Clay	Silty Clay	Silty Clay			-
Material Description:	Fill	Fill	Fill	Fill	Fill	Fill	****		
To Be Used As	354882E	354880E	354877E	354861E	354864E	354860E			
Carrella Location	5782202N	5782219N	5782234N	5782208N	5782228N	5782258N			
Sample Location :	Layer 1	Layer 1	Layer 1	Layer 1	Layer 1	Layer 1			
				175	175	175			
Layer Depth (mm):	175	175	175	175	150	150			
Test Depth (mm):	150	150	150		AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)			
Sampling Procedure:	AS1289.1.2.1.6.4(b)	AS1289.1.2.1.6.4(b)		AS1289.1.2.1.6.4(b) 19.0	19.0	19.0			
Max Size (mm):	19.0	19.0	19.0	0	0	0		A CONTRACTOR OF THE CONTRACTOR	
Oversize Wet (%):	0	0	0	2.09	2.07	2.07			
Fld. Wet Density (t/m³) AS 1289.5.8.1:	2.08	2.13	2.02	2.09	2.01	2. 10.			
Fld. Moisture Content (%) AS1289.2.1.1:	-	-	-	0.44	2.05	2.01			
PCWD (t/m³):	2.03	2.07	2.04	2.11		2.01			
APCWD (t/m³)	-	-	-	-	-	-			
O.M.C (%) AS1289.5.7.1:	•		-	-	-				
Moisture Ratio (%) AS1289.5.4.1:			-	-		0 F0/ (
Moisture Variation (of omc):	0.5% (wet)	1% (wet)	0.5% (wet)	1% (wet)	0.5% (wet)	0.5% (wet)			
Adjusted Moisture Variation (of omc):	-	-	•	-	ļ	011			
Compactive Effort:	Standard	Standard	Standard	Standard	Standard	Standard			
Hilf Density Ratio (%):	102.5	103.0	99.5	99.0	100.5	103.0			
Min Hilf Density Ratio (%):	95	95	95	95	95	95			

Remarks:



NATA Anzeitator No 12719 Accredited for compliance with ISO/IEC 17025. The results of tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

APPROVED SIGNATORY

Issue Date: 19/02/2013

Form No.: CG.315.002

M.Robinson

Ph: +61 3 8796 7900 Fax: +61 3 8796 7944



Customer: Grosevnor Lodge Pty Ltd

Customer Address: 48 Healy Road, Dandenong Sth, Vic 3175

Project: Meridian Estate

Location: Clyde North

Customer Order No.: -

HILF DENSITY RATIO REPORT

Report Number:

380735 - 48

Report Date: 08/09/16

C.G Order No: -

Test Method: AS1289.5.7.1

Page: 1 of 1

Testing performed and reported at our Dandenong South Laboratory 21712

1610555									
1									
-									
7/09/2016									
pm									
8/09/2016									
Site Derived									
Silty Clay									
Fill									
Meridian Estate									
E354716									
N57828414									
0									
2.03									
-									
1.95									
-									
-									
-									
2.5% (dry)									
-									
Standard									
104.5									
95									
	1 -7/09/2016 pm 8/09/2016 Site Derived Silty Clay Fill Meridian Estate E354716 N57828414 Roadway 200 150 A\$1289.1.2.1.6.4(b) 19.0 0 2.03 - 1.95 2.5% (dry) - Standard 104.5	1	1	1	1	1 7/09/2016 pm 8/09/2016 Site Derived Sitty Clay Fill Meridian Estate E354716 N57828414 Roadway 200 150 AS1289.1.2.1.6.4(b) 19.0 0 2.03 1.95 1.95 1.95 2.5% (dry) Standard 104.5	1	1	7/09/2016

Remarks:





Accredited for compliance with ISO/IEC 17025. The results of tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

APPROVED SIGNATORY

Form No.: CG.315.002

Issue Date: 19/02/2013

A. Catton





Dandenong South ACN 143 009 330 25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W17DS00439

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123 Meridian Estate

Project: Meridian Est **Project No.:** 3807351

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing

ts of the tests, calibrations and/or Approved Signatory: M. Robinson

ents includes in this occurrent eable to Australian/national (Senior Technician)

12712 Date of Issue: 30/05/2017

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Stage 5

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample Data						
Sample ID	S17DS-01650	S17DS-01651	S17DS-01652	S17DS-01653	S17DS-01654	
Field Sample ID	1	2	3	4	5	
Date Tested	8/05/2017	8/05/2017	8/05/2017	8/05/2017	8/05/2017	
E	354861	354801	354774	354816	354861	
N	5782283	5782273	5782306	5782323	5782334	
				Retest		
Soil Description	Clay	Clay	Clay	Clay	Clay	
Field and Laboratory Data						
Depth of Test (mm)	150	150	150	150	150	
Depth of Layer (mm)	200	200	200	200	200	
Oversize Wet (%)		2				
Field Wet Density (t/m³)	2.17	2.10	2.18	1.98	2.01	
Peak Converted Wet Density (t/m³)	2.00	2.12	2.05	2.11	2.10	
Compactive Effort	Standard	Standard	Standard	Standard	Standard	
Moisture Variation (%)	0.5 dry	0.5 wet	0.0	0.5 wet	0.0	
Hilf Density Ratio (%)	108.5	99.5	106.5	94.0	95.5	





Dandenong South ACN 143 009 330 25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W17DS02277

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate Clyde Stage 7

Project No.: 3807351.007

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing

reditation No. 12719

ulls of the tests, calibrations and/or ments included in this document are le to Australian/hational standards.

Approved Signatory: M. Robinson (Senior Technician)

12712 Date of Issue: 14/11/2017
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S17DS-08395			
Field Sample ID	1			
Date Tested	10/11/2017			
E	354820			
N	5782321			
Soil Description	Clay			
Field and Laboratory Data				
Depth of Test (mm)	150			
Field Wet Density (t/m³)	2.02			
Peak Converted Wet Density (t/m³)	1.95			
Compactive Effort	Standard			
Moisture Variation (%)	3.0 dry			
Hilf Density Ratio (%)	103.5			

\sim				
	om	1441		TC
\mathbf{C}		ши	CI I	10





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02116

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







er results of the tests, calibrations and/or surrements included in this document are:

Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 30/09/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S19DS-07421	S19DS-07422		
Field Sample ID	1	2		
Date Tested	25/09/2019	25/09/2019		
Location	354728	354730		
E	5782312	5782287		
Soil Description	Clay	Clay		
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Wet Density (t/m³)	2.10	2.07		
Peak Converted Wet Density (t/m³)	2.04	2.00		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	3.0 wet	0.0		
Hilf Density Ratio (%)	103.0	103.5		





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02117

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







ne results of the tests, calibrations and/or Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 30/09/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S19DS-07423			
Field Sample ID	1			
Date Tested	25/09/2019			
Location	354757			
E	5782359			
Soil Description	Clay			
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
AS Sieve Size (mm)	19.0			
Oversize Wet (%)	0			
Field Wet Density (t/m³)	2.03			
Peak Converted Wet Density (t/m³)	1.87			
Compactive Effort	Standard			
Moisture Variation (%)	3.0 dry			
Hilf Density Ratio (%)	108.5			





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02123

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







ne results of the tests, calibrations and/or Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 30/09/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements:

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S19DS-07438	S19DS-07439
Field Sample ID	1	2
Date Tested	26/09/2019	26/09/2019
Location	354721	354737
E	5782364	5782314
N	RL 31.05 m	RL 31.12 m
Soil Description	Clay	Clay
Depth of Test (mm)	150	150
Depth of Layer (mm)	200	200
AS Sieve Size (mm)	19.0	19.0
Oversize Wet (%)	2	0
Field Wet Density (t/m³)	2.03	2.05
Peak Converted Wet Density (t/m³)	2.01	2.05
Compactive Effort	Standard	Standard
Moisture Variation (%)	2.0 dry	1.0 dry
Hilf Density Ratio (%)	101.5	100.0





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02133

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







re results of the tests, calibrations and/or asurements included in this document are

Approved Signatory: M. Robinson

(Team Leader)

12712 Date of Issue: 4/10/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample ID	S19DS-07464	S19DS-07465		
Field Sample ID	1	2		
Date Tested	30/09/2019	30/09/2019		
E	354731	354738		
N	5782321	5782285		
	RL 30.70 m	RL 30.86		
Soil Description	Clay	Clay		
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Wet Density (t/m³)	2.05	2.04		
Peak Converted Wet Density (t/m³)	1.89	2.02		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	3.0 dry	2.0 dry		
Hilf Density Ratio (%)	108.5	101.0		

\sim	_	-		•	_	-	40
C	U	Ш	Ш	Ш	е	Ш	ts



Project:



Dandenong South ACN 143 009 330

25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02143

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123 Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







he results of the tests, calibrations and/or assurements included in this document are Approved Signatory: M. Robinson

(Team Leader)

12712 Date of Issue: 4/10/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample ID	S19DS-07519			
Field Sample ID	1			
Date Tested	1/10/2019			
E	354716			
N	5782349			
	RL 30.88 m			
Soil Description	Clay			
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
AS Sieve Size (mm)	19.0			
Oversize Wet (%)	0			
Field Wet Density (t/m³)	2.06			
Peak Converted Wet Density (t/m³)	2.07			
Compactive Effort	Standard			
Moisture Variation (%)	2.0 wet			
Hilf Density Ratio (%)	99.5			

\mathbf{c}	m	m	01	+-
Cc)	ш	ei	เเธ



Project:



Dandenong South ACN 143 009 330

25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02154

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123 Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







The results of the tests, calibrations and/or neasurements included in this document are Approved Signatory: M. Robinson

(Team Leader)

12712 Date of Issue: 2/12/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample ID	S19DS-07546	S19DS-07547		
Field Sample ID	1	2		
Date Tested	2/10/2019	2/10/2019		
E	354726	354711		
N	5782286	5782328		
	RL 30.80 m	RL 30.70 m		
Soil Description	Clay	Clay		
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Wet Density (t/m³)	2.06	2.03		
Peak Converted Wet Density (t/m³)	2.08	2.07		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	0.5 wet	2.0 wet		
Hilf Density Ratio (%)	99.0	98.0		

\sim	_			_		4_
	n	100	m	Δ	i a t	œ
	v	ш	ш	·	ш	U





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02168

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







ne results of the tests, calibrations and/or Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S19DS-07582	S19DS-07583		
Field Sample ID	1	2		
Date Tested	3/10/2019	3/10/2019		
Location	354735	354702		
E	5782298	5782379		
N	RL 31.26 m	RL 30.56 m		
Soil Description	Clay	Clay		
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Wet Density (t/m³)	2.04	2.01		
Peak Converted Wet Density (t/m³)	2.02	2.08		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	1.0 wet	3.0 wet		
Hilf Density Ratio (%)	101.0	97.0		



Project:



Dandenong South ACN 143 009 330

25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02181

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123 Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







The results of the tests, calibrations and/or easurements included in this document are Approved Signatory: M. Robinson

(Team Leader)

12712 Date of Issue: 16/01/2020
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S19DS-07613	S19DS-07614	S19DS-07615	S19DS-07616	
Field Sample ID	1	2	3	4	
Date Tested	4/10/2019	4/10/2019	4/10/2019	4/10/2019	
Location	354895	354891	354722	354726	
E	5782729	5782689	5782332	5782300	
N	RL 31.10 m	RL 31.17 m	RL 31.28 m	RL 31.15 m	
Soil Description	Clay	Clay	Clay	Clay	
Depth of Test (mm)	150	150	150	150	
Depth of Layer (mm)	200	200	200	200	
AS Sieve Size (mm)	19.0	19.0	19.0	19.0	
Oversize Wet (%)	0	0	0	0	
Field Wet Density (t/m³)	2.07	2.07	2.05	2.08	
Peak Converted Wet Density (t/m³)	1.97	2.02	2.01	2.07	
Compactive Effort	Standard	Standard	Standard	Standard	
Moisture Variation (%)	2.0 dry	0.5 dry	2.0 dry	0.5 dry	
Hilf Density Ratio (%)	105.0	102.5	101.5	100.5	





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02199

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







of the tests, calibrations and/or the included in this document are:

Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 98% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-07662	S19DS-07663		
Field Sample ID	1	2		
Date Tested	7/10/2019	7/10/2019		
Location	Summit	Summit		
	354684	354700		
	5782388	5782276		
	RL: 29.647	RL: 29.990		
Soil Description	CLAY	CLAY		
Depth of Test (mm)	175	175		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Wet Density (t/m³)	2.00	2.03		
Peak Converted Wet Density (t/m³)	1.96	2.05		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	0.5 dry	0.0		
Hilf Density Ratio (%)	102.0	99.0		





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02229

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







er results of the tests, calibrations and/or Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 98% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-07778			
Field Sample ID	1			
Date Tested	10/10/2019			
Location	354765			
	5782241			
	RL: 31.17			
Soil Description	CLAY			
Depth of Test (mm)	200			
Depth of Layer (mm)	175			
AS Sieve Size (mm)	19.0			
Oversize Wet (%)	0			
Field Wet Density (t/m³)	2.11			
Peak Converted Wet Density (t/m³)	2.03			
Compactive Effort	Standard			
Moisture Variation (%)	2.0 dry			
Hilf Density Ratio (%)	104.0			

\mathbf{c}	1	m	01	+-
Cc	Ш	ш	ei	เเธ





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02242

Issue No: 2

This report replaces all previous issues of report no 'HDR:W19DS02242'.

Accredited for compliance with ISO/IEC 17025







No.12219

Approved Signatory: M. Longfield

susements included in this occurrient are cosable to Australianiational standards.

12712 Date of Issue: 11/11/2019

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: CG Request No.:

TRN: Lot No.:

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 98% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-07816	S19DS-07817	S19DS-07818		
Field Sample ID	1	2	3		
Date Tested	11/10/2019	11/10/2019	11/10/2019		
Location	354767	354745	354764		
	5782295	5782221	5782212		
	RL: 31.96	RL: 30.83	RL: 30.85		
Soil Description	CLAY	CLAY	CLAY		
Depth of Test (mm)	175	175	175		
Depth of Layer (mm)	200	200	200		
AS Sieve Size (mm)	19.0	19.0	19.0		
Oversize Wet (%)	0	0	0		
Field Wet Density (t/m³)	1.92	2.00	2.04		
Peak Converted Wet Density (t/m³)	1.97	2.09	2.08		
Compactive Effort	Standard	Standard	Standard		
Moisture Variation (%)	0.5 dry	2.0 wet	0.5 wet		
Hilf Density Ratio (%)	97.0	95.5	98.0		





25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02250

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: **CG Request No.:**

TRN: Lot No.: Accredited for compliance with ISO/IEC 17025 – Testing







Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported Material: General Fill

Sample ID	S19DS-07838	S19DS-07839	S19DS-07840	S19DS-07841	
Field Sample ID	1	2	3	4	
Date Tested	14/10/2019	14/10/2019	14/10/2019	14/10/2019	
Location	354741	354753	354777	354762	
	5782259	5782213	5782203	5782242	
	RL: 31.16	RL: 31.07	RL: 31.25	RL: 31.22	
Soil Description	CLAY	CLAY	CLAY	CLAY	
Depth of Test (mm)	175	175	175	175	
Depth of Layer (mm)	200	200	200	200	
AS Sieve Size (mm)	19.0	19.0	19.0	19.0	
Oversize Wet (%)	0	0	0	0	
Field Wet Density (t/m³)	2.03	2.04	2.02	2.01	
Peak Converted Wet Density (t/m³)	2.04	2.10	2.13	2.08	
Compactive Effort	Standard	Standard	Standard	Standard	
Moisture Variation (%)	0.0	2.0 wet	0.0	0.0	
Hilf Density Ratio (%)	99.5	97.0	95.0	96.5	





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02261

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







ne results of the tests, calibrations and/or Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: meridian estate stage 9B

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Material:

Sample ID	S19DS-07873	S19DS-07874
Field Sample ID	1	2
Date Tested	15/10/2019	15/10/2019
E:	354772	354749
N:	5782224	5782219
	31.167	31.045
Soil Description	clay (general fill)	clay (general fill)
Depth of Test (mm)	175	175
Depth of Layer (mm)	200	200
AS Sieve Size (mm)	19.0	19.0
Oversize Wet (%)	0	0
Field Wet Density (t/m³)	2.12	2.08
Peak Converted Wet Density (t/m³)	2.12	2.15
Compactive Effort	Standard	Standard
Moisture Variation (%)	0.0	0.0
Hilf Density Ratio (%)	100.0	96.5





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02276

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







er results of the tests, calibrations and/or asurements included in this document are

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-07942	S19DS-07943	S19DS-07944	
Field Sample ID	1	2	3	
Date Tested	16/10/2019	16/10/2019	16/10/2019	
Location	354739	354773	354775	
	5782254	5782208	5782302	
	RL: 31.44	RL: 31.52	RL 32.16	
Soil Description	CLAY	CLAY	CLAY	
Depth of Test (mm)	175	175	175	
Depth of Layer (mm)	200	200	200	
AS Sieve Size (mm)	19.0	19.0	19.0	
Oversize Wet (%)	0	0	0	
Field Wet Density (t/m³)	2.13	2.10	2.14	
Peak Converted Wet Density (t/m³)	2.14	2.13	2.14	
Compactive Effort	Standard	Standard	Standard	
Moisture Variation (%)	0.0	0.0	0.0	
Hilf Density Ratio (%)	100.0	98.5	100.0	





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02292

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







e results of the tests, calibrations and/or
Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-07996	S19DS-07997	S19DS-07998		
Field Sample ID	1	2	3		
Date Tested	18/10/2019	18/10/2019	18/10/2019		
Location	354751	354742	354763		
	5782252	5782208	5782203		
	RL: 31.52	RL: 31.67	RL: 31.73		
Soil Description	CLAY	CLAY	CLAY		
Depth of Test (mm)	175	175	175		
Depth of Layer (mm)	200	200	200		
AS Sieve Size (mm)	19.0	19.0	19.0		
Oversize Wet (%)	0	0	0		
Field Wet Density (t/m³)	2.08	2.05	1.88		
Peak Converted Wet Density (t/m³)	2.02	2.02	1.92		
Compactive Effort	Standard	Standard	Standard		
Moisture Variation (%)	0.5 dry	2.0 dry	1.0 wet		
Hilf Density Ratio (%)	102.5	101.5	98.0		





25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02315

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







er results of the tests, calibrations and/or Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-08059			
Field Sample ID	1			
Date Tested	22/10/2019			
Location	354774			
	5782190			
	RL: 31.85			
Soil Description	CLAY			
Depth of Test (mm)	200			
Depth of Layer (mm)	175			
AS Sieve Size (mm)	19.0			
Oversize Wet (%)	0			
Field Wet Density (t/m³)	1.89			
Peak Converted Wet Density (t/m³)	1.92			
Compactive Effort	Standard			
Moisture Variation (%)	0.0			
Hilf Density Ratio (%)	98.5			

\mathbf{c}	1	m	01	+-
Cc	Ш	ш	ei	เเธ





Dandenong South ACN 143 009 330

25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W19DS02329

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9B

Project No.: 3807351.009B

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







e results of the tests, calibrations and/or surements included in this document are.

Approved Signatory: M. Longfield

(Senior Technician)

12712 Date of Issue: 11/11/2019
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde Nth

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Imported

Material: General Fill

Sample ID	S19DS-08110			
Field Sample ID	1			
Date Tested	23/10/2019			
Location	354784			
	5782265			
	RL: 32.20			
Soil Description	CLAY			
Depth of Test (mm)	175			
Depth of Layer (mm)	200			
AS Sieve Size (mm)	19.0			
Oversize Wet (%)	0			
Field Wet Density (t/m³)	2.09			
Peak Converted Wet Density (t/m³)	2.06			
Compactive Effort	Standard			
Moisture Variation (%)	0.0			
Hilf Density Ratio (%)	101.0			

Comments





Dandenong South ACN 143 009 330

25 Metcalf Street
DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W20DS00028

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 9

Project No.: 3807351.009

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing







er results of the tests, calibrations and/or surpressing included in this document are Approved Signatory: M. Robinson

(Team Leader)

12712 Date of Issue: 16/01/2020
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S20DS-00102			
Field Sample ID	1			
Date Tested	13/01/2020			
Location	354778			
E	5782402			
N	RL 32.657			
Soil Description	Clay			
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
AS Sieve Size (mm)	19.0			
Oversize Wet (%)	0			
Field Wet Density (t/m³)	1.95			
Peak Converted Wet Density (t/m³)	1.91			
Compactive Effort	Standard			
Moisture Variation (%)	0.0			
Hilf Density Ratio (%)	102.0			

\sim	100 100	
CO		ents

Appendix D: Controlled fill certificates



PROJECT: Lot No: 9082 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE : August 2020

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9083 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9084 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9085 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9086 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9087 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9088 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9089 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9090 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9091 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9092 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9093 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9094 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9095 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9096 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9097 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9098 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9099 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9100 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9101 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9102 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9103 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9104 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9105 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9106 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9107 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9108 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9109 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9110 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9111 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9112 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE : August 2020

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9113 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9114 Chadwick Geotechnics REF: 3807351.09C.v1

: August 2020

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9115 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 9116 Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: GG Chadwick Geotechnics REF: 3807351.09C.v1

Meridian Estate Stage 9C

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

DANDENONG SOUTH VIC 3164

DATE : August 2020

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection (17 May 2016 to 23rd October 2019). No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Lober Border

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



